





# **MONUMENT RECORD**


STATE OF INDIANA-COUNTY OF MONROE

Section: 3, Township: 8 NORTH, Range: 2 WEST,

Monument Description & Remarks: R.R. SPIKE FOUND 4" BELOW GRADE IN CENTERLINE  
SOUTHEAST CORNER OF SECTION 3

## **Recovery Tie Drawing**

A=  R.R. SPIKE  
 B=  STOP SIGN  
 C=  P.K. NAIL IN POWER POLE  
 D=  P.K. NAIL IN POWER POLE




Section Corner: R.R. SPIKE FOUND

Northing: 1421924.777 Easting: 3086900.054


State Plan Coordinate (NAD83 Survey Feet, Indiana West Zone)

I, Eric Lee Deckard, here by certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; this 8th day of OCTOBER, 2004 A.D.

Completed by Steven V. Farkas Monroe County Surveyor



Indiana Registered Land Surveyor No. LS 29900012



## MONUMENT RECORD



STATE OF INDIANA - COUNTY OF MONROE

SECTION 3, TOWNSHIP 8 North, RANGE 2 West

## MONUMENT DESCRIPTION &amp; REMARKS

Railroad spike in center line of road at intersectionof Kirby Rd. and Gifford Rd.

## RECOVERY TIE DRAWING



(●) AT CORNER



NOT TO SCALE

STATE OF INDIANA

COUNTY OF Monroe

I, Edmund O. Farkas HEREBY CERTIFY THAT THIS DOCUMENT WAS PREPARED UNDER MY DIRECTION IN ACCORDANCE WITH THE PROVISIONS OF SECTION 17-3-64-4 - 17-3-64-8 OF THE INDIANA CODE, BEING ACTS OF 1965, CHAPTER 319; AND THE ABOVE DATA IS GIVEN UNDER MY HAND AND SEAL THIS \_\_\_\_\_ DAY OF \_\_\_\_\_, 19\_\_\_\_ A.D.

SPACE  
RESERVED  
FOR  
RECORDING  
OFFICER.

INDIANA REGISTERED LAND SURVEYOR NO. \_\_\_\_\_

OR \_\_\_\_\_

UNITED STATES GOVERNMENT AGENCY

TOWNSHIP:  
Van Buren

CORNER I.D.

TITLE